

SECRET

Copy 1 of 5

13 APR 1960


MEMORANDUM FOR: Record

SUBJECT : Operational Appraisal of Mission 1562,
1563, and 4156, System VII

1. Enclosed herewith is the operational appraisal of Missions 1562, 1563, and 4156.

- a. Mission 1562 - System VII equipments functioned properly
- b. Mission 1563 - System VII equipments functioned properly. The 14-channel tape was received with one side of the metal reel so badly bent that replacing was necessary to perform read-out of the tape.
- c. Mission 4156 - System VII equipments functioned properly.

2. To permit faster read-out of the 14-channel system it would help if the time of lock ons, when possible, could be indicated on the System VII check sheets.



25X1A

Chief, ELINT Branch, ED/SI

HANDLE VIA TALENT
CONTROL SYSTEM ONLY